ಜಿಲ್ಲಾ ಅಗ್ನಿತಾಮಕ ಅಧಿಕಾರಿಯವರ ಕಥೇರಿ ಕರ್ನಾಟಕ ರಾಜ್ಯ ಅಗ್ನಿತಾಮಕ ಮತ್ತು ಸುರ್ತು ಸಂವರ್ಗಳು. ಭೀದರ ಜಿಲ್ಲೆ, ಬಂದರ-588401,

Karnataka State Fire

CNO/ 11 /DFO/BIDAR/Advice/2023

And Emergency Services

Date: 15/04/2023

To,

The Principal Sri Kalora Lingeshwar English Medium School Humnbad Tq Humnbad District Bidar.

R/sir.

Sub:-

Issue of "Fire Safety Recommendations" Sri Kalora

Lingeshwar English Medium School Humnbad Tq Humnbad

District Bidar.

Ref :-

Applicants letter on Date: 28/03/2023

With reference to the subject above cited, the premises Sri Kalora Lingeshwar English Medium School Humnbad Tq Humnbad District Bidar was inspected by, me on 08/04/2023 with respect to fire prevention, fire fighting and evacuation measures to be Provided in the above premises building details as under.

A. Details of the Building/Premises:-

01	A. Details of the Building/Prei Name and Address of the Applicant.		The Principal Sri Kalora Lingeshwar English Medium School Humnbad Tq Humnbad District Bidar.
02	Name and Address of the premises.		Sri Kalora Lingeshwar English Medium School Humnbad Tq Humnbad District Bidar.
03	Name and address of the Building owner		President Sri Vivekananda Education Societys Humnbad tq Humnbad District Bidar
04	Number of buildings	4	01 No's of Building.
05	Number of floors	1	Ground floor+01
06	Floor-wise details of occupancy:-		
	Ground floor		08 class room, 01 library, chemistry lab 01, biology lab 01, staff room 01, computer lab 01, office room 01, principal room 01, waiting room 01,
	First floor	1	12 class room, hall 01, waiting room 01, office room 01, principal 01, computer lab, staf room 01.
07	Height of the building	1	6.90 mtrs

PRESIDENT
Sri Vivekananda Education Scolety
HUMNABAD - 585 330
Dist. Bidar.



PRINCIPAL

SRI KALORA LINGESHWAR

English Medium School

HUMNABAD, Dist, Bidar (K.S.)

	Principle Steel					
08	Site area		38393.00sqmtrs			
09	Built-up area of each floor:-					
02	- Ground floor		1479.01 Sqmtr	er cancer and account of the contract of		
-	First floor		1295 99 Sqmtr			
10	Total built-up area Total		2775 sq mtrs			
11	Surrounding properties -					
_	East	5	Agriculture land			
- 1	West					
72.0	North (frount) :		N H 65 road			
	South	-	Open plot			
12	Set-back area available around the building -					
16	East		03 mtrs	The set of 50		
	West	- Inc	03 mtrs	around the		
	North (frount)		03 mtrs than play ground	building to be maintained as per		
	South		03 trs than play ground	zonal regulations		

B. On inspection of this Educational premises, the following fire prevention: fire fighting and evacuation measures are recommended & are considered absolutely essential from fire safety point of view:-

SI. No. [01]	Details [02]	Existing [03]				Recommendations [04]
01	Accessibility to Premises.	The premises is accessible from 09 mtrs wide Road Located on Northen side side				Adequate
02	No of entrances.	01 No. of Entrance				Adequate
03	No. of staircases available	No of staircase		01	02	Adequate
		Width of staircase	:	L50 Mtr	1.50 Mtr	
		Width of treads	1	30 cm	30 cm	
		Height of		1.5 cm	15 cm	

PRESIDENT
Sri Vivekananda Education Scole
HUMNABAD - 585 330
Dist, Bidar,

testing may be the



PRINCIPAL SRI KALORA LINGESHWAR English Medium School HUMNABAD, Dist. Bidar (K.S.)

	riser per flight		10	10	
	Height of handrails		01.0 0 Mtrs	01.00 Mtrs.	
	Head room clearance		03 Mtrs	03 Mtrs	
04 Fire extinguisher	Not	Pr	ovided		O1) 04 no's ABC Fire Extinguisher each of S 1'g capacity in each floor O2) 02 no's ABC The Extinguisher each of S 1'g capacity & 01 No of CO2 Fire Extinguisher each of 3.2 kg capacity. O3) O1 No of CO2 extinguisher of 4.5 kg capacity near the Electrical Switch board. O4) 10 No's of sand Bucket for Electrical Switch board. O5) Two number of Hand gloves near the Electrical Switch board. O6) O1 No's Water Missi type extinguishers of O9 liters capacity should be kept near each staircase landing at each floor. O7) O1 No Mechanical Foam FE of 9 Ltrs capacity and O1 No ABC FE of 6 kg capacity should provide near Diesel Generator. [All the extinguishers suggested above should be suggested above should be suggested.

PRESIDENT
Sri Vivekananda Education Scolety
HUMNABAD - 585 330
Dist. Bidar.

PRINCIPAL
SRI KALORA LINGESHWAR
English Medium School
HUMNABAD, Elst. Didar (K.S.)

			should be located at an easily accessible position without obstructing the gardened passage and maintained periodically] Of No of Hose reel hose of	
	Hose reel hose system.	Not Provided.	30 mtr length with drain and 01 no's delivery hose papes minimum 2½ inch size of adequate length to reach the farthest point of each that off branch having a nozzle of 2 mm size. The hose teel hose has been connected at each landing by means of an adapter.	
06	At the terrace tank level with minimum pressure of 3.5 kg/cm2	Not Provided.	To Provide 01 No pump with minimum pressure of 3.5 kg/sqcm.	
07	Diesel generators.	Not Provided	Diesel Generator of 15 1 Capacity should be provide and it should be connected to alternate power supply	
08	Terrace tank.	2000 ltrs capacity for School Purpose	Provide 10000 hr water Capacity RCC Structure terrace tank for Fire Fighting purpose.	
09 Escape routes		Not Marked.	Direction in which the students have to move in the event of an emergency should be displayed in the corridor in each fl. or du has evacuation. The Notice board have been	
10	Fire order (Fire Safety Plans)	Not Displayed	indicted the action should to	

PRESIDENT
Sri Vivekananda Education Scolety
HUMNABAD - 585 330
Dist Bidar.

PRINCIPAL
O SRI KALORA LINGESHWAR
English Medium School
CHUMNABAD, Dist, Bidar (K.S.)

			case of any emergency should be displayed with the telephone number of Humnbad fire Station i.e-08483-270264, 112 & 101and the telephone number of nearest Ambulance services and Police Station.
11	No Smoking Board	Not Displayed	COTPA Sec-4 Direction No. Smoking area Smoking Lear is an offence Board Should be written in English & Kannada both language Shall be Prominently displayed at inside the Entry/Exist of Each Floor.
12	Fire Siren	Not Installed	A fire Siren shall be installed in the premises to inform the inmates in case of a fire emergency and evacuate the area.
13	Nominate one fire Nodal officer	Texas	A fire nodal officer shall be nominated either from teaching or no teaching staff
14	Fire fighting training,	Not Imparted	At-least 40% of School Staff should be got trained in basic fire fighting at R.A.Mundkur fire & Emergency Services Academy, Bannerughatta road, Bangalore within 3 months or at an early date
15	Fire Precautionary Measures	Not provided.	Explosive and flammable materials should not be stored in the store room UPS room. Electrical panel area, class room laboratory and electrical cum panel premises. 2) Accumulation of combustible waste in and

Sri.Vivekanchera Edicht stient Scelety
HUMNADAD +635 330
Dist. Bidar.

PRINCIPAL BALCHONAS
SRI KALORA LINGESHWAR English Medium School
HUMNABAD, Dist, Bidar (K.S.)

promises around the should be avoided.

3) The exit ways shall be always kept clear v. Lac. any Obstruction.

4) Liquefied petroleum mas should not be stored in

the building.

5) The doors shall not be kept locked / latehed during working hours and shall be free from obstruction.

6) During the class hours the class room doors shall not be locked from inside to outside.

As per that so supreme court occur teachers and staffs shall be trained to handle salety mitate equipment. emergency evacuation and protect their students in the event of fire and other emergency and the school shall observe the fire safety day on 14th of every year by conducting fire salety and s with co-ordinate with it v

Hence this "Fire Safety Recommendation" is issued to Sri Kalona Lingeshwar English Medium School Humnbad Tq Humnbad District Bidar subject to strict adherence of the conditions as laid down in this Recommendations and to check the portable fire extinguishers & hose reel hose system & pump system to conduct mock drills periodically And the management must not extend the height of the building beyond 15.0 meters, and this Recommendations is valid for a period of one year from the date of issue.

Sri Vivekananda Education Scolet\$RI KALORA LINGESHWA HUMNABAD - 585 330 English Medium School

Dist. Bidar.

DISTRICT FIRE OFFICER HUMNABAD, Dist. Bidar Karnetaka Fire & Emergency Service

Your's faithfully

Fire Station, BIDAR